Dart Aerospace Ltd. Thursday, 16/08/2007 11:32:44 AM Date User Linda Lacelle **Process Sheet** : STEP WELDME : CU-DAR001 Dart Helicopters Services **Drawing Name** Customer Jot Number : 34027 **Estimate Number** : 12577 : NA : D3562042 Part Number P.C. Number S.O. No. : 1 : D3562 UNDER REVIEW : 16/08/2007 This Issue **Drawing Number** : N/A Prsht Rev. Project Number Type : LARGE FAB ASSY First Issue **Drawing Revision** : 33580 Previous Run Material Each Qtv: **Due Date** Written By Checked & Approved By New Issue 06-11-09 JLM Comment Additional Product Jot Number: **Machine Or Operation:** Description: Seq. #: 1.0 D2622120C Extrusion Comment: Qty.: 1.0000 Each(s)/Unit Total: 5.0000 Each(s) Qtv Part # Description 334066 D2622-120C Extrusion Check Material for any Dents or Defects 206 Step Endplate 2.0 D2734 Comment: Qty.: 2.0000 Each(s)/Unit Total: 10.0000 Each(s) Pick: Description, Batch End Cap 334485 **Qty Part Number** 2 D2734 3.0 LARGE FAB 1 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 07.10.04 1-Cut D2622 extrusion as per Dwg D3562 0 m 07.10.04

3-Weld (1)end cap as per Dwg D3562& QSI 004. Inspect for foreign objects as per QSI 0

Aluminum Rod

4-Grind end cap welds flush as per Dwg D3562

W /O:		WORK ORDER CH	WORK ORDER CHANGES						
DATE STEP		PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
				•,	*				
							•		
							-		
							l		

Part No: ______ PAR #: _____ Fault Category: ______ NCR: Yes No DQA: ____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:	WORK ORDER NON-CONFORMANCE (NCR							
		Description of NC		Corrective Action Section B	Verification	Annaval	Ammanal	
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
		Tak e						
							:	

Dat :: Thursday, 16/08/2007 11:32:44 AM Linda Lacelle User: **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services **Drawing Name: STEP WELDMENT** Job Number: 34027 Part Number: D3562042 cob Number: Seq. #: **Machine Or Operation:** Description: INSPECT WORK TO CURRENT STEP 4.0 QC5 Comment: INSPECT WORK TO CURRENT STEP VISUAL WELDING INSPECTION 5.0 QC9 Comment: VISUAL WELDING INSPECTION 6.0 HAND FINISHING HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 QC3 7.0 POWDER COAT/CHEMICAL CONVERSION ARM WELDMENT 8.0 D3560042 Comment: Qty.: 1.0000 Each(s)/Unit Total: 5.0000 Each(s) ARM WELDMENT 9.0 D3560044 ARM WELDMENT Comment: Qty.: 1.0000 Each(s)/Unit Total: 5.0000 Each(s) ARM WELDMENT Batch: **B3447** 10.0 Comment: Qty.: 36.0000 Each(s)/Unit Total: 180.0000 Each(s) Blind Rivet batch: M105125 11.0

Comment: SMALL & MEDIUM FAB RESOURCE 1

Drill Rivet holes as per dwg D3562. Touch up alodine.

□age 2

W /O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
01-10 M		Split who	It	07.10.11	4						
				,							

Part No:	_ PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
			QA: N/C C	losed:	Date:

NCR:			ER NON-CONFORMAN	CE (NCR)				
		Description of NC		Corrective Action Section B				A
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector
						,		
								-
				· · · · · · · · · · · · · · · · · · ·			,	
				•				
					,			
	نر ا							

Date: Thursday, 16/08/2007 11:32:44 AM Linda Lacelle User: **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services **Drawing Name: STEP WELDMENT** Job Number: 34027 Part Number: D3562042 ob Number: Seq. #: Description: **Machine Or Operation:** 07,10,10 Rivet legs using Magnabond as per dwg D3562. Ensure to wipe off any exess magnobond of the step A/R Magnabond 6398 12.0 QC5 Comment: INSPECT 13.0 LARGE FAB LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 1-Weld Remaining end cap as per Dwg D3562& QSI 004. Inspect for foreign objects as per QSI 024. Aluminum Rod 1103 794 2-Grind end cap welds flush as per Dwg D3562 VISUAL WELDING INSPECT 14.0 QC9 **Comment: VISUAL WELDING INSPECTION** 15.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP POWDER COATING 16.0 POWDER COATING 105068 Comment: POWDER COATING Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 17.0 HAND FINISHING RESOURCE #1 HAND FINISHING1 Comment: HAND FINISHING RESOURCE #1 Wing Walk as per Dwg D3562 and QSI 005 4.4

Batch: M 105694

FL 07/10/18 (5



W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
04.70,	业 18 i	Put bushing D2808 #B32896 on Sleps	mF.	07-10- 24	5					
A(w(24	业化	ingroud QCH5		Alalzq	5		Co Halzy			

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date: MINDS
			OA: N/C CI	ocod:	Date:

NCR:		W	ORK OR	DER NON-CONFORMANCE	(NCR)			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section B Action Description Chief Eng	Sign &	Verification Section C	Approval Chief Eng	Approval QC Inspector
cActio	华	Derry inspection A forgin object was bend in the Jekp After the CARS were welded. P.C. Humman error	1 / /	Dr.11 small hile form end cap to renare form diself. Clear and Remare debis Re relid hale as per DSTOWY Re impact benefacts	0.11.16	- Osteolib	Sour	Shedis Shedis

Dat a: 1

Thursday, 16/08/2007 11:32:44 AM

User:

Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: STEP WELDMENT

Job Number: 34027

Part Number: D3562042

cob Number:



Seq. #:

Machine Or Operation:

Description:

18.0

INSPECT POWDER COAT/CHEMICAL CONVERSION

Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

PACKAGING RESOURCE #1

10-10-0

19.0



Comment: PACKAGING RESOURCE #1

Pick Assembly Kit



20.0





Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



U St. (0.2)

W/O:		WORK ORDER CHANGES									
DATE	STEP	P PROCEDURE CHANGE				Approval Chief Eng / Prod Mgr	Approval QC Inspector				
		•									
		•				. # ₃					

Part No:	PAR #:	Fault Category:	 NCR: Yes	No	DQA:	Date: _	
			QA: N	/C C	losed:	Date: _	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification	Anneous	Anneous			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector			
					·						
							·				
							ı				
	·							-			
				÷							
							!				

10/4/24

00

07 $\boldsymbol{\omega}$ \triangleright .06. .19 07.01.15 90 07.06 .09 .26 9 DRAWING N STEP MON **ARMS** NEW ISSUE ASSEMBLY MAGBND MOM RIVETED **AEROS** ADD ONTARIO, D2808, 7 SPACE L STEP RMV SHEET 윾 SIN